National Transportation Safety Board NTSB ID: FTW94LA003 Aircraft Registration Number: N9762B FACTUAL REPORT Occurrence Date: 10/01/1993 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone **DFW AIRPORT** TX 75261 2344 CDT Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft CESSNA 208B Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On October 1, 1993, at 2344 central daylight time, a Cessna 208B, N9762B, was substantially damaged following a loss of control while taxiing at the Dallas Fort Worth International Airport (DFW), Texas. The airline transport rated pilot was not injured.

Visual meteorological conditions prevailed for the 14 CFR Part 135 on demand air taxi flight.

According to the pilot, the all cargo flight operating under the call sign "Martinaire 639" departed Tulsa, Oklahoma, at 2201 on an IFR flight plan. A normal approach and landing were executed to Runway 17R at the DFW Airport. The pilot was instructed to hold short of Runway 17L, on taxiway 18, prior to taxiing to the northeast cargo area.

According to the enclosed ATC transcript, Martinaire 639 was instructed to cross Runway 17L at 2236:53, behind a heavy MD-11 that was previously cleared for takeoff at 2235:53. Prior to issuing the clearance to cross, the pilot was issued a wake turbulence caution. The pilot stated that as he was in the process of crossing the runway, the MD-11 advanced its engines to takeoff power. The jet blast from the departing MD-11 struck the Cessna 208B and "blew my aircraft off of the runway."

The left wing impacted the ground resulting in structural damage to the wing spar.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW94LA003

Occurrence Date: 10/01/1993

AVIATION		Occurrence Type: Accident											
Landing Facility/Approach Inf	formation												
Airport Name	Airport ID:	Airport Eleva	tion	Runv	vay Used	Runwa	Runway Length		Runway V	Vidth			
DFW INTERNATIONAL	ITERNATIONAL DF			603 Ft.	. MSL	. 17R	ł	11388	3		200		
Runway Surface Type: Concrete													
Runway Surface Condition: Dry													
Type Instrument Approach:													
VFR Approach/Landing: None													
Aircraft Information													
Aircraft Manufacturer CESSNA			Model/ 208B						Serial 208B	Numbei 80109			
Airworthiness Certificate(s): Normal													
Landing Gear Type: Tricycle													
Homebuilt Aircraft? No	omebuilt Aircraft? No Number of Seats: 1						8750 LBS Numbe			er of Eng	gines: 1		
Engine Type: Turbo Prop	Engine Manufacturer: Model/Series: P&W PT6A-114							Rated I 600 H		wer:			
- Aircraft Inspection Information													
Type of Last Inspection	Date of Last	ice Last Insp	ection		Airfram	ne Total Ti	me						
AAIP	08/08/1993 168 Hours						ours		3435	Hours			
- Emergency Locator Transmitter (ELT) Information													
ELT Installed? Yes			ELT	Aided in	Locating A	ccident S	ite?						
Owner/Operator Information													
Registered Aircraft Owner	Street Address P.O BOX 308												
CESSNA FINANCE CORPOR	City WICHITA									Code 01			
	Street Address												
										0 - 1 -			
MARTINAIRE, INC.	DALLAS							TX	e ∠ip 752:				
Operator Does Business As: Operator Designator Code: GPMA													
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s):	: On-demand Air	Taxi											
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Under: Part 135: Air Taxi & Commuter													
Type of Flight Operation Conducted	d: Unknown												
		FACTU	AL REPO	RT - AVIATI	ON						P	age 2	
Owner/Operator Information Registered Aircraft Owner CESSNA FINANCE CORPOR Operator of Aircraft MARTINAIRE, INC. Operator Does Business As: - Type of U.S. Certificate(s) Held: Air Carrier Operating Certificate(s): Operating Certificate: Regulation Flight Conducted Under	: On-demand Air	Taxi	City Street A	P.O BOX WICHITA Address 8030 AV	(308 A IATIC	ON PLAC	CE, #2000				762 e Zip 752	Coc 35	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW94LA003

Occurrence Date: 10/01/1993

AVIATION				Occurrence Type: Accident										
First Pilot Information														
Name City								City				Date	e of Birth	Age
On File	On Fil	n File On File On File						File	37					
Sex: M Seat Occupied: Left Principal Profession: Civilian Pilot Certificate Number: On File														
Certificate(s): Airline Transport; Flight Instructor														
Airplane Rating(s): Multi-engine Land; Single-engine Land														
Rotorcraft/Glider/LTA: None														
Instrument	Rating(s): Airpl	lane												
Instructor Rating(s): Airplane Single-engine														
Type Ratin	g/Endorsement fo	or Accident/In	ncident Aircra	ft? No			C	urrent Bie	ennial F	light Re	view?			
Medical Cert.: Class 1 Medical Cert. Status: Valid Medicalw/ waivers/lim.									Dat	e of Las	t Medical	Exam	: 02/22/19	93
									•					
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night A		Ir Actual	Instrument Simulated		Rotorcra	t	Glider	Lighter Than Air
Total Time		2740	598	1009	1731	432		1;	34	51				
Pilot In Cor	mmand(PIC)	2357	598	954	1400	427		1:	34	51				
Instructor		1039		1039		55			10					
Last 90 Da	ys	347	327	348	1		180		35	1				
Last 30 Da	-	116	111	117			72	,	13	1	_			
Last 24 Ho		5	5	5		 	2		1					
Seatbelt Us	sed? Yes	Shou	ılder Harness	Used? Yes			Toxicology Performed? No Second Pilot? No)	
	n/Itinerary													
71	ght Plan Filed: IF	R				ı								
Departure Point							State Air		Airport Identifier		Dep	Departure Time		Time Zone
TULSA								TUL			2201			CST
<u>Destination</u> State								А	Airport Identifier					
Same as Accident/Incident Location														
Type of Clearance: IFR														
Type of Airspace: Class B; Class D; Class E														
Weather Information														
Source of Briefing: Commercial Weather Service; Flight Service Station														
Method of Briefing:														

FACTUAL REPORT - AVIATION

Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW94LA003

Occurrence Date: 10/01/1993

Occurrence Type: Accident

	c1 1 BO.														
Weather	Information														
WOF ID	Observation Time	Time Zone	WOF	Elevati	on	WOF D	WOF Distance From Accident Site				Direction From Accident Site				
DFW	2350	CDT		603 Ft.	MSL		1 NM				270 Deg. Mag.				
Sky/Lowes	st Cloud Condition: Clea		0 Ft. AGL						Condition of Light: Night/Dark						
Lowest Ceiling: None				0 Ft. AGL			ility:	20	SM	Altimeter: 29.00		"Hg			
Temperatu		17 °C	°C Wind Direction: 180 Density								Ft.				
Wind Spee		Weather Condtions at Accident Site: Visual Conditions													
Visibility (F	(RVV)	0	SM	M Intensity of Precipitation: Unknown											
Restrictions to Visibility: None															
Type of Pr	Type of Precipitation: None														
Accident	Information														
Aircraft Da	Air	Aircraft Fire:						losio	n						
Classification:															
- Injury Su	ıry Summary Matrix Fatal Serious Minor None TOTAL														
First Pi	ilot					1		1							
Second	d Pilot														
Studen	nt Pilot														
Flight I	nstructor														
Check	Pilot														
Flight E	Engineer														
Cabin /	Attendants														
Other (Crew														
Passer	ngers														
- TOTAL A	ABOARD -					1		1							
Other 0	Ground	0	(0			0							
- GRANE	D TOTAL -	0			0	1 1									
				•	'			•							

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: FTW94LA003

Occurrence Date: 10/01/1993

Occurrence Type: Accident

A I ' ' ' '	
Administrative	Intormation
Autililionalive	IIIIOIIIIauoii

Investigator-In-Charge (IIC)

HECTOR R. CASANOVA,

Additional Persons Participating in This Accident/Incident Investigation:

GENE M BLAND FAA FSDO DALLAS, TX 75247